

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18TH STREET - SUITE 500
DENVER, CO 80202-2466
http://www.epa.gov/region08

Ref: 8EPR-SR

February 15, 2000

Ms. Celia VanDerLoop City and County of Denver Department of Environmental Health 1391 Speer Boulevard, Suite 700 Denver, CO 80204-2558

RE: Vasquez Boulevard/ Interstate 70 NPL Site, Phase III Data

Dear Celia:

Enclosed please find electronic files of the sampling data from the Phase III Field Investigation for the Vasquez Boulevard/Interstate 70 Site. These files include all data collected during the period of August, 1999 -December, 1999 in accordance with the Phase III Field Investigation Project Plan. As you review the files please note the following:

- 1. The data has been validated, data qualifiers are in columns separate from the numerical value.
- 2. We have included the calculation of the 95% upper confidence limit on the arithmetic mean (95 UCL) for the yard soil arsenic concentrations. Please note that in cases where the 95UCL for the yard is greater than the highest measured value, the exposure point concentration that will be used in the baseline risk assessment will be the highest measured value consistent with EPA guidance (OSWER Publication 9285.7-081, Supplemental Guidance to RAGS: Calculating the Concentration Term).
- 3. We have included the year of construction information that is available to EPA. You will note that this information is only available for a limited number of properties.
- 4. A few properties are designated as commercial. These are residential properties that have been acquired by the Colorado Department of Transportation.

I have also enclosed a summary table of the Phase III field investigation for your information. As always, if you have any questions about this information, please call me at (303) 312-6579.

Sincerely,

Bonnie Lavelle

Remedial Project Manager

enclosures

INITIAL PHASE III SAMPLING PROGRAM SUMMARY

	CLAYTON	COLE	ELYRIA	FIVE POINTS	GLOBE VILLE	SWANSEA	TOTAL
PROPERTY ACCESS							
Target Properties	1044	967	91	22	42	444	2610
Access Granted	661	609	48	14	22	219	1573
Access Granted, Not Sampled	25	6	0	0	0	. 0	31
Access Granted, Insufficient Area for Sampling	0	7	2	1	2	1	13
Sampled w/o Access	7	3	1	0	0	′ 4	15
Access Denied	19	11	5.	2	1	13	51
PROPERTY SAMPLING							
Residential Soil	644	603	47	14	22	220	1550
Schools	2	2	0	0	0	0	4
Parks	0	1	0	0	0	0	1
TOTAL	646	606	47	14	22	220	1555
Gardens	7	9	1	0	0	2	19
Indoor Dust	21	25	5	5	6	14	76

INITIAL PHASE III FIELD ANALYTICAL PROGRAM SUMMARY

Field Samples	5847
Blind Duplicates	254
Lab Duplicates	262
Blind Standards	152
Lab Control Samples	954
Instrument Blanks	412
Method Blanks	90
MDL Study Samples	194
Proficiency Samples	92
Variability Test Samples	72
Other Test Samples	118
TOTAL	8447